SDMS US EPA REGION V -1

SOME IMAGES WITHIN THIS DOCUMENT MAY BE ILLEGIBLE DUE TO BAD SOURCE DOCUMENTS.

MEMORANDU M

DATE:

October 16, 1987

TO:

T. Ayers

FROM:

R. L. Johnson'- On Scene Representative - Collinsville Region

SUBJECT:

1631210006 - St. Clair County - Sauget/Monsanto-Krummrich Drum

Superfund/Technical

Reference: RLJ Memos dated September 22 & 33, 1987.

In the past two weeks, construction activity at the Krummrich Drum site has dealt exclusively with placement of the clay cap. Site driveby's were conducted on October 5, 9, & 16, 1987.

On the last visit, this writer was stopped outside the gate to the site by a Monsanto employee. An invitation onto the site was offered but declined so that even tacit Agency approval could not be implied by this writer's presence. The contractor, GeoCon, Inc., had difficulty locating clay which could achieve design permeability of 10^{-6} cm/sec. The material currently being placed achieves a permeability of 10^{-9} cm/sec, but meeting design criteria of optimum moisture and density is extremely difficult under field conditions. The project is behind schedule due to these factors.

On-site conditions have changed very little in the past two weeks. (Photos #745-#22 & #23) Level B PPE and the GeoCon trailer were dismissed after the completion of the surface grading.

RLJ:jlr/0315L

cc: J. Larson

cc: DLPC - Collinsville

RECEIVE -OCT 20 1987 IEPA/DLFC DATE: October 9, 1987

TIME: 1:20 p.m.

D. 1631210006

St. Clair County

Sauget/Monsanto-Krummrich

PHOTOGRAPH TAKEN TOWARD THE:

Northwest

OLL# 745 PHOTO# 22



GFUTEXICES

ATE: October 9, 1987

IME: 1:20 p.m.

SITE CONDITIONS, TO RIGHT

OF TRUCKS IS STAGED

. 1631210006

St. Clair County

Sauget/Monsanto-Krummrich

TOTOGRAPH TAKEN TOWARD THE:

Northwest

PHOTO# 23

HOTOGRAPH BY:

OLL# 745

Tx Colorador

SITE CONDITIONS - PEACING

